

# Oil Field Environmental Incident Summary

**Incident:** 20150306132615      **Date/Time of Notice:** 03/06/2015 13:26

**Responsible Party:** Golden Eagle Trucking,inc.

**Well Operator:** RIM OPERATING, INC.

**Well Name:** BOSS 12-17

**Field Name:** STOCKYARD CREEK

**Well File #:** 14792

**Date Incident:** 3/4/2015      **Time Incident:** 04:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 99

**Sec:** 17

**Qtr:** SW NW

**Location Description:** Spill originates on Boss 12-17 well site, then ran down road and ditch to the south east off of well site.

**Submitted By:** Jon Putnam

**Received By:**

**Contact Person:** Waylon Olsen  
5 INVERNESS DRIVE EAST  
ENGLEWOOD, CO 80112

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident** Truck Overflow

**Release Contained in Dike** No

**Reported to NRC:** Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	40	Barrels	10	Barrels		
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No immediate risk.

**Areal Extent:**

**Potential Environmental Impacts:**

Soil in coulee absorbed the salt water.

**Action Taken or Planned:**

Sucked up surface liquid. We will have to excavate top soil and dispose of material. Placed absorbent bouies in coulee.

**Wastes Disposal Location:** Closest solids disposal site.

**Agencies Involved:**

**Updates**

---

**Date:** 3/6/2015

**Status:** Reviewed; Followup Required

**Staff:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

---

**Date:** 3/9/2015

**Status:** Inspected; More Followup Required

**Staff:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

3/9/2015 at 11:55, on location. Oil staining visible next to tank battery on top of hill in flow path release took toward the creek; however, no oil staining visible on hill slope or at bottom next to creek.

According to report contact, at time of release the spill had not reached the creek. However, with recent meltwater the creek has risen and has inundated the impacted area.

Excavator is on site, and it appears some scraping of spill endpoint has been performed.

EC readings:

Upstream of impact location next to lease road culvert, within the flow: 381 uS

Adjacent to spill endpoint on upstream side in still water: 313 uS

Adjacent to spill endpoint on downstream side in still water: 1341 uS

Downstream of spill endpoint along creek: all readings <350 uS

Quantab on water with the 1341 uS EC reading = 55 ppm

Meeting with report contact tomorrow to discuss further work.